



Califat Coal Mine, St George's Hill, Swannington

Photographic Report Of LIHS Excavation - December 2021

Califat Engine House



The session focussed on moving bricks, and more bricks, and yet more bricks from various piles around the engine house. They were wheelbarrowed to the Alabama engine house site.

Alabama Engine House



Broken bricks were tipped and full bricks stacked at the Alabama site.



Califat Coal Mine, St George's Hill, Swannington

Photographic Report Of LIHS Excavation - December 2021

Miners Cottages



More of the French drain at the rear of the cottage was uncovered.