



## Califat Coal Mine, St George's Hill, Swannington Photographic Report Of LIHS Excavation - November 2022

### Alabama Engine House



The focus was digging down to a consistent level across the site.



The hole in the tiered brickwork descending from the memorial stones, shows that the brick structure surrounds a large internal hollow.





## **Califat Coal Mine, St George's Hill, Swannington**

### **Photographic Report Of LIHS Excavation - November 2022**



The mounds of broken bricks and excavated soil have grown considerably during the year.

### **Miners' Cottages**



Work continued at the cottages, with the membrane being used to minimise weeds and protect the brickwork from frost.